




C.01 = C.04 (2x)

ESCALA 1:40




C.02 = C.03 (2x)

ESCALA 1:40




C.05 = C.06 = C.22 = C.23 (4x)

ESCALA 1:40




C.07 a C.21 = C.24 (16x)

ESCALA 1:40



### ESTRIBOS DAS CINTAS

ESCALA 1:20



RESUMO			
Ø (mm)	Compr. (m)	Press. (kg)	
5 Ø4-60	0,00	886	0
6,3 Ø4-50	354,80	886	0
8 Ø4-50	285,60	106	0
10 Ø4-50	587,20	306	0
12,5 Ø4-50	107,20	1065	0
15 Ø4-50	0,00	0	0
20 Ø4-50	0,00	0	0
Soma =			2 473
Vigas (V)			1
Total =			2 473

TABELA DE FERROS			
Pos	h	Compr.	Total (m)
23	10	8	6,00
24	10	24	11,00
25	10	16	3,60
26	10	16	3,60
27	6,3	7,60	1,10
28	12,5	8	4,15
29	8	8	3,65
30	12,5	80	2,80
31	12,5	80	3,30
32	6	40	5,95
33	6,3	16,70	1,85
34	12,5	24	5,35
35	12,5	40	11,90
36	6,3	1108	177,80

CONCRETO fck = 25,0 MPa